

## Project

Project name	
Project date	11/08/2022
Job End Date	11/08/2022



## Table of Contents

Project name	Project number	Project date
		<b>11/08/2022</b>

Project Information .....	P-1
Section: 1;MH1 - MH2 .....	1
Section:2;MH2-MH3 .....	5
WinCan .....	8



## Project Information

Project name	Project number	Project date <b>11/08/2022</b>
--------------	----------------	-----------------------------------

### Contractor

Company: Orbital Underground Service Location Pty Ltd  
Responsible person: Jamie Ware  
Division:  
Street: 69 Henderson Road  
City: Sheldon, Queensland 4157  
Phone: 1300 ORBITAL  
Fax:  
Mobile:  
E-Mail: jamieware@orbital.com.au


## Section Inspection - 11/08/2022 - 1

Date of inspection <b>11/08/2022</b>	Time of inspection <b>13:59</b>	Land Ownership	Pipe Asset ID <b>1</b>	Nr. <b>1</b>
Project name	Contractor's Job Number	Coding Standard <b>WSA 05-2008 2.2</b>	Name of operator <b>Jamie Ware</b>	Job ID <b>4189</b>

Town	US MH <b>MH1</b>	Unit Length <b>0.00 m</b>	
Address	Direction <b>Upstream</b>	GIS length <b>0.00 m</b>	
Location Type <b>Easement</b>	DS MH <b>MH2</b>	Inspected Length <b>12.93 m</b>	
Operation <b>Storm water drain</b>	Use <b>Drain</b>	Year Laid	

Profile <b>375mm</b>	Purpose of inspection <b>Operational Condition Inspection</b>	
Lining Material	Method of inspection <b>Television Camera</b>	
Lining Type	Precipitation <b>No precipitation</b>	
Dia/Height <b>375 mm</b>	Cleaning <b>The conduit was not cleaned prior to the inspection</b>	
Material <b>Concrete pipe</b>	Flow control <b>No measures taken</b>	

General comment

1:113	m+	Code	Observation Text	MPEG	Photo	Grade
<b>MH2</b>						
	0.00	STMH	Start node, maintenance hole, Nodename:, MH2	00:00:00	1_b851db 90-8355-4 dd8-869b-	
	0.00	WLC	Water level, clear flow (the invert is visible), water level: 0%	00:00:22	1_46e48fd 8-da88-43 c9-87d2-1	
	0.00	CCW	Circumferential wall crack, width: 2mm from 12 o'clock to 12 o'clock	00:00:24	1_bc7360f 2-6c4f-451 8-b05d-6f5	1
	0.33	JDL	Displaced joint, longitudinal displacement, longitudinal displacement: >30mm at 12 o'clock	00:02:02	1_640bf76 d-9fac-40b f-b8b1-c92	2
	0.33	SRVP	Steel reinforcement is visible and projecting into the conduit, at joint from 9 o'clock to 5 o'clock	00:02:05	1_6b540bf c-e687-4b e2-911c-c	
	2.79	JDL	Displaced joint, longitudinal displacement, longitudinal displacement: >30mm at 12 o'clock	00:03:48	1_609d39c 6-3de4-49 52-b427-8	2
	2.79	BM	Breaking, some pieces are missing, at joint, length of break: 100mm at 2 o'clock / Broken spigot	00:04:01	1_7b1e37 1c-4a57-4 159-8b7e-	5
	5.23	JDL	Displaced joint, longitudinal displacement, longitudinal displacement: 21-30mm at 12 o'clock	00:06:00	1_e141f3d 4-8ddd-4fb 3-a2ac-7b	1
	7.49	BM	Breaking, some pieces are missing, at joint, length of break: 100mm at 9 o'clock	00:07:49	1_1a7c329 5-c7ce-45 24-89e3-7	5
	7.64	CLS	Longitudinal surface crack, at joint, width: 1mm at 9 o'clock	00:07:52	1_7cc0c38 b-218b-4f9 a-900d-23	1
	10.23	JDL	Displaced joint, longitudinal displacement, longitudinal displacement: 10-20mm at 12 o'clock	00:09:06	1_1f98394 2-07af-46b b-bb51-4a	1
	12.93	FMHM	Finish node, maintenance hole, Nodename:, MH1	00:10:10	1_1d845e d1-0190-4 290-b800-	
<b>MH1</b>						

Construction Features

Miscellaneous Features

Structural Defects

Service &amp; Operational Defects

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
8	60.0	10.3	133.6	5	0	0.0	0.0	0.0	1

## Section Pictures - 11/08/2022 - 1

Town	Address/Location	Date of inspection	Pipe Asset ID	Job ID
		11/08/2022	1	4189



1\_b851db90-8355-4dd8-869b-627495cf1608\_20220811\_135941\_021.jpg, 00:00:00, 0.00  
Start node, maintenance hole, Nodename:, MH2



1\_46e48fd8-da88-43c9-87d2-15a080f03879\_20220811\_140009\_964.jpg, 00:00:22, 0.00  
Water level, clear flow (the invert is visible), water level: 0%



1\_bc7360f2-6c4f-4518-b05d-6f5037d6a297\_20220811\_140054\_291.jpg, 00:00:24, 0.00  
Circumferential wall crack, width: 2mm from 12 o'clock to 12 o'clock



1\_640bf76d-9fac-40bf-b8b1-c9247a7c5d5e\_20220811\_140313\_540.jpg, 00:02:02, 0.33  
Displaced joint, longitudinal displacement, longitudinal displacement: >30mm at 12 o'clock

## Section Pictures - 11/08/2022 - 1

Town	Address/Location	Date of inspection	Pipe Asset ID	Job ID
	,	11/08/2022	1	4189



1\_6b540bfc-e687-4be2-911c-c8dc1e484ca1\_20220811\_140459\_056.jpg, 00:02:05, 0.33  
Steel reinforcement is visible and projecting into the conduit, at joint from 9 o'clock to 5 o'clock



1\_609d39c6-3de4-4952-b427-81ec529ef3f0\_20220811\_140725\_863.jpg, 00:03:48, 2.79  
Displaced joint, longitudinal displacement, longitudinal displacement: >30mm at 12 o'clock



1\_7b1e371c-4a57-4159-8b7e-25aba316bc81\_20220811\_140911\_870.jpg, 00:04:01, 2.79  
Breaking, some pieces are missing, at joint, length of break: 100mm at 2 o'clock / Broken spigot



1\_e141f3d4-8ddd-4fb3-a2ac-7b4198ba411e\_20220811\_141132\_172.jpg, 00:06:00, 5.23  
Displaced joint, longitudinal displacement, longitudinal displacement: 21-30mm at 12 o'clock

## Section Pictures - 11/08/2022 - 1

Town	Address/Location	Date of inspection	Pipe Asset ID	Job ID
	,	11/08/2022	1	4189



1\_1a7c3295-c7ce-4524-89e3-7b3c108df658\_20220811\_141346\_311.jpg, 00:07:49, 7.49  
Breaking, some pieces are missing, at joint, length of break: 100mm at 9 o'clock



1\_7cc0c38b-218b-4f9a-900d-23252f57c2ed\_20220811\_141420\_824.jpg, 00:07:52, 7.64  
Longitudinal surface crack, at joint, width: 1mm at 9 o'clock



1\_1f983942-07af-46bb-bb51-4a4a8a776d95\_20220811\_141627\_952.jpg, 00:09:06, 10.23  
Displaced joint, longitudinal displacement, longitudinal displacement: 10-20mm at 12 o'clock



1\_1d845ed1-0190-4290-b800-888ec4aacf67\_20220811\_141751\_201.jpg, 00:10:10, 12.93  
Finish node, maintenance hole, Nodename:, MH1


## Section Inspection - 11/08/2022 - 2

Date of inspection <b>11/08/2022</b>	Time of inspection <b>14:24</b>	Land Ownership	Pipe Asset ID <b>2</b>	Nr. <b>2</b>
Project name	Contractor's Job Number	Coding Standard <b>WSA 05-2008 2.2</b>	Name of operator <b>Jamie Ware</b>	Job ID <b>4189</b>

Town	US MH <b>MH2</b>	Unit Length <b>0.00 m</b>	
Address	Direction <b>Downstream</b>	GIS length <b>0.00 m</b>	
Location Type <b>Easement</b>	DS MH <b>MH3</b>	Inspected Length <b>10.15 m</b>	
Operation <b>Storm water drain</b>	Use <b>Drain</b>	Year Laid	

Profile <b>375mm</b>	Purpose of inspection <b>Operational Condition Inspection</b>	
Lining Material	Method of inspection <b>Television Camera</b>	
Lining Type	Precipitation <b>No precipitation</b>	
Dia/Height <b>375 mm</b>	Cleaning <b>The conduit was not cleaned prior to the inspection</b>	
Material <b>Concrete pipe</b>	Flow control <b>No measures taken</b>	

General comment

1:89	m+	Code	Observation Text	MPEG	Photo	Grade
<b>MH2</b>						
						
	0.00	STMH	Start node, maintenance hole, Nodename:, MH2	00:00:00	<a href="#">2_a1ccb371-f6f2-41b6-9916-f09</a>	
	0.00	WLC	Water level, clear flow (the invert is visible), water level: 0%	00:00:18	<a href="#">2_522194c7-3e11-41cb-ae8a-9</a>	
	0.54	JDL	Displaced joint, longitudinal displacement, longitudinal displacement: 10-20mm at 12 o'clock	00:01:58	<a href="#">2_ccad764b-72a3-4b07-8223-4</a>	1
	2.91	JDL	Displaced joint, longitudinal displacement, longitudinal displacement: 10-20mm at 12 o'clock	00:02:52	<a href="#">2_a5729d3b-4510-4955-8516-</a>	1
	7.84	JDL	Displaced joint, longitudinal displacement, longitudinal displacement: 10-20mm at 12 o'clock	00:04:55	<a href="#">2_84634ada-02b3-4ee7-84fd-3</a>	1
	7.84	CCW	Circumferential wall crack, at joint, width: 1mm from 11 o'clock to 1 o'clock	00:05:01	<a href="#">2_86d8aeb3-9bf2-4faa-9b34-8</a>	1
	10.15	FHMH	Finish node, maintenance hole, Nodename:, MH3	00:05:54	<a href="#">2_8575c63a-614f-48f5-8620-7e</a>	
<b>MH3</b>						

Construction Features

Miscellaneous Features

Structural Defects

Service &amp; Operational Defects

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
4	1.0	0.2	2.5	1	0	0.0	0.0	0.0	1

## Section Pictures - 11/08/2022 - 2

Town	Address/Location	Date of inspection	Pipe Asset ID	Job ID
		<b>11/08/2022</b>	<b>2</b>	<b>4189</b>



2\_a1ccb371-f6f2-41b6-9916-f0905a8550a7\_20220811\_142450\_746.jpg, 00:00:00, 0.00  
 Start node, maintenance hole, Nodename:, MH2



2\_522194c7-3e11-41cb-ae8a-98216a695492\_20220811\_142517\_563.jpg, 00:00:18, 0.00  
 Water level, clear flow (the invert is visible), water level: 0%



2\_ccad764b-72a3-4b07-8223-4d4b797a7550\_20220811\_142712\_039.jpg, 00:01:58, 0.54  
 Displaced joint, longitudinal displacement, longitudinal displacement: 10-20mm at 12 o'clock



2\_a5729d3b-4510-4955-8516-465be0dd0164\_20220811\_142822\_015.jpg, 00:02:52, 2.91  
 Displaced joint, longitudinal displacement, longitudinal displacement: 10-20mm at 12 o'clock

## Section Pictures - 11/08/2022 - 2

Town	Address/Location	Date of inspection	Pipe Asset ID	Job ID
	,	11/08/2022	2	4189



2\_84634ada-02b3-4ee7-84fd-36fca8b637e2\_20220811\_143040\_353.jpg, 00:04:55, 7.84  
Displaced joint, longitudinal displacement, longitudinal displacement: 10-20mm at 12 o'clock



2\_86d8aeb3-9bf2-4faa-9b34-8e133b939c95\_20220811\_143110\_651.jpg, 00:05:01, 7.84  
Circumferential wall crack, at joint, width: 1mm from 11 o'clock to 1 o'clock



2\_8575c63a-614f-48f5-8620-7e83d79b1442\_20220811\_143220\_680.jpg, 00:05:54, 10.15  
Finish node, maintenance hole, Nodename:, MH3

## WinCan

### Notes:

Thank you for choosing to use WinCan to carry out your drainage investigation works.

The results and views carried in this report are those of the engineer(s) appointed to carry out the investigation and are considered relevant on the day of the survey. Drain and sewer performance is known to alter over time, so liability cannot be accepted for differences between the recorded data and the actual data at a time after this report was generated.

This survey has been created in accordance with the drainage standard used in the country and language settings for this PC.

If a DVD has been supplied with this report, please note that it can only be used in a Windows based PC. Please browse the DVD and navigate to the PDF folder to find project-based documents such as drawings, engineer's site notes and survey specifications amongst others.

CCTV subsidence investigations do not account for the water tightness of the pipes and are merely a visual inspection of inside of the drains. CCTV drainage engineers are generally not qualified to comment on the causes of subsidence, and can only suggest required remedial actions for the pipes, and not the affected buildings.

Subsidence is a building structural failure, which can occur for many reasons. Although drainage failures can contribute to subsidence problems, other causes should always be investigated as part of a considered approach. In order to eliminate drains from suspicion, WinCan suggests that all pipes within at least 10m of the subsidence area be pressure tested over and above a CCTV inspection, and remedial suggestions considered based on the findings.

Unless otherwise specified in an associated task order (or similar), the data gathered in this report may not be suitable for use as a pre-lining investigation. WinCan are happy to carry out such surveys, but this must be agreed prior to the commencement of the works, and the client must specify the data they wish to capture and the acceptable tolerances.

Where GPS coordinates and heights have been issued within this report, they are to 1m accuracy, and 2m accuracy for heights. Greater accuracy can be provided on request.